

INACTIVE STATUS

62-22868-93 now supplied by Norton in a kit with 276 instructions included and foam packed individually.

04/30/03

CONVERTED PART
SECOND SOURCE PART
CARD YES NO

NO. 790
DATE _____ REV. _____

P/N 62-22868-93
DESCRIPTION IGNITOR KIT (NORTON)
SET-UP BY LARRY STEC APPROVED BY [Signature]
DATE MAY 16, 1994

PARTS USED IN CONVERTING PART

1	1) P/N <u>62-22868-02</u>	DESC <u>IGNITOR</u>
1	2) P/N <u>276</u>	DESC <u>STUFFER</u>
	3) P/N _____	DESC _____
	4) P/N _____	DESC _____
	5) P/N _____	DESC _____
	6) P/N _____	DESC _____
	7) P/N _____	DESC _____
	8) P/N _____	DESC _____

STATUS | **REASON FOR CONVERSION**
 ONE TIME ONLY | (CHECK ONE OR MORE)
 TEMPORARY | 1) _____ 3) _____ 5) _____
 PERMANENT | 2) _____ 4) _____ 6)

INIT. REQ. AT TIME OF BUILD _____ DATE _____ | IS PART A SAFETY DEVICE
 YES _____ NO _____

LABEL 3
 STANDARD LABEL **COUNT** _____ **INITIAL** _____
 SPECIAL LABEL _____

SPECIAL INSTRUCTIONS:

THIS PART IS ONLY PURCHASED TO MAKE THIS PCF AND WILL NOT BE SOLD SEPARATELY.

PART HISTORY

SALES _____ (ROLLING YEAR)
 TOTAL ON HAND _____
 FS _____ MV _____ GV _____
 BRANCHES: _____ LV _____
 CL _____ PX _____ TS _____

PARTS TO BE MADE AT THIS TIME: _____
 WITH THESE INSTRUCTIONS _____
 _____ PER _____
 LS BT BH LS

ACTUAL NUMBER BUILT _____
 REASON FOR DIFFERENCE _____

WAREHOUSE REPRESENTATIVE SIGNATURE _____
 JC BR BH

NEW DN _____
 (IF APPLIES)

YES
 NO SEE _____ FOR SPECIAL INSTRUCTIONS/HANDLING.

- 1) EXPEDITED ORDER, NEED TO SHIP ASAP
- 2) EMERGENCY
- 3) ONLY METHOD OF HAVING (NLA) PART
- 4) LEAD TIME NOT ACCEPTABLE
- 5) QUANTITY PURCHASE DOESN'T ALLOW BUYING PART.
- 6) STOCK REWORK OR KIT

* SPECIAL LABELS SHOULD BE KEPT FOR FUTURE REFERENCE.
 ▲ SEE BOB T./ LARRY S. FOR INSTRUCTIONS BEFORE BUILDING ANY FUTURE CONVERSIONS OF THIS PART.

- CC: M. BURCHAM
 B. THOMAS
 C. HOLCOMBE
 L. SMITH
 S. BROWN
 P. DOYLE
 A. HUMPHREY
 L. KELTON
 B. HILTS
 A. FUTCH M.V.